


# P. L. C Application Equipment

## WSP-4XS 4-Axis Position Control Trainer



- Main Voltage
  - 1 Phase AC 220~240V / 50/60HZ
- Digital Input & Output Connection Points
  - Input : 27 & Output : 6
- Air is necessary for operation
- Sensor Type : NPN Type
- Providing operation manual

※ P. L. C Controller is not included

## WSP-2X 2 Axis Position Control Trainer



- Main Voltage
  - 1 Phase AC 220~240V / 50/60HZ
- Digital Input & Output Connection Points
  - Input : 20 & Output : 10
- Air is necessary for operation
- Sensor Type : NPN Type
- Providing operation manual

※ P. L. C Controller is not included

01

02

03

04