


P. L. C Application Equipment

WSP-1B Drill Machine Trainer



- Main Voltage
 - 1 Phase AC 220~240V / 50/60HZ
 - Digital Input & Output Connection Points
 - Input : 10 & Output : 7
 - Air is necessary for operation
 - Sensor Type : NPN Type
 - Controller (PLC) is not included
 - Providing operation manual
- ※ P. L. C Controller is not included

WSP-1C Product Supply Robot Trainer



- Main Voltage
 - 1 Phase AC 220~240V / 50/60HZ
 - Digital Input & Output Connection Points
 - Input : 8 & Output : 6
 - Air is necessary for operation
 - Sensor Type : NPN Type
 - Controller (PLC) is not included
 - Providing operation manual
- ※ P. L. C Controller is not included

* Product's design and appearance can be changed without any notice.