


P. L. C Application Equipment

WSV-1 Belt Conveyor Trainer



- Main Voltage
 - 1 Phase AC 220~240V / 50/60HZ
 - Digital Input & Output Connection Points
 - Input : 10 & Output : 11
 - Sensor Type : NPN Type
 - Air is necessary for operation
 - Providing operation manual
- ※ P. L. C Controller is not included

WSS-1 Air Robot Trainer



- Main Voltage
 - 1 Phase AC 220~240V / 50/60HZ
 - Digital Input & Output Connection Points
 - Input : 13 & Output : 8
 - Sensor Type : NPN Type
 - Air is necessary for operation
 - Providing operation manual
- ※ P. L. C Controller is not included

※ All P. L. C application equipments can be controlled by all of PLC such as SIMENS, MITSUBISHI, LS, Allen-Bradley